

Safety Measures

Always protect your sight by wearing quality safety goggles. This is a highly alkaline product, similar to portland cement in chemical composition.

•Should the product come in contact with your eyes, flush eyes with water immediately and consult a physician.

Always wear rubber gloves to protect skin from exposure to this product.

•Should the product come in contact with skin, rinse with water, wash with soap and rinse. If irritation persists, consult a physician.

Always wear a particle mask while mixing and pouring this product.

•Inhalation or ingestion of this product produces the same symptoms as cement or quicklime. Do not eat, drink, or smoke during mixing or pouring. Exposed clothing should be removed.

Do not look directly into the poured hole for ten hours. A blowout may occur. A blowout is caused by improper use of this product. To prevent a blowout always follow guidelines and procedures. A blowout may occur three or more times. Do not go into the affected area. Observe safety rules and recommended precautions.



HELPFUL TIPS

1. Core temperature and hole diameter will determine the correct product.
2. Always use clean, cold water.
3. Always wear safety goggles, gloves, and a particle mask while handling product.
4. Never look directly into poured hole.
5. Barricade and stay out of poured area for ten hours.
6. Use proper hole pattern for your application.
7. Store in dry conditions.
8. Never use this product for any purpose but cracking rock or concrete.
9. Read and follow the manufacturer's directions.